

# Digimatic Gap & Step Gauges



## FEATURES

- Used for checking the mutual position of two adjacent surfaces
- Zero setting at any position,
- Power supply: One LR44 battery
- Function: On/Off, Origin (Zero setting), Data output, inch/mm.
- Made of stainless steel

## SPECIFICATIONS & DIMENSIONS

Order No.	Range	Resolution	Accuracy ( $\pm$ )
158-030	-10-30mm	0.01mm/0.0005"	0.02mm

